

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242339
Address: 2614 SW BARLEY FIELD DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|---|---------------|----------|-------------------------|
| All Rough Inspection - Residential | Shawn Hoffman | Failed | Friday, August 02, 2024 |

Corrective Action Required:

2 Misc

2614 SW Barelyfield dr
Fb = Fire block or draft stop

- Fb top plate penetrations at closest and switch in bedroom 2
- In bedroom 2 nail exterior stud corners to code
- Solid block sheeting break at South side of living room window
- Provide anchor bolt at plate break at exterior wall of single bay garage
- Not able to inspect framing of patio cover (closed up)
- No pressure on gauge for gas piping

Comments: