

## **EVERSTEAD**

3741 NE TROON DR LEE'S SUMMIT, MO 64064 (816) 399-4901

Inspector				ction Date	Time		
Derek Perez				AUG '24	0650		
Address City		Permi	t #	Owner/Builder			
600 NE Maquire BLVD Lee's Summit			PR	PRCOM20234376 ABI			
			Subdivision		Lot#		
Foundat	tion						
Site Conditions (all must comply if applicable)			Slab (Basement or Garage As Marked)				
<ul> <li>✓ Erosion control is in place and functional (inspection shall not be performed if erosion control is not functionally in compliance with the City requirements).</li> <li>✓ Soils – bearing capacity as determined by:</li> <li>✓ Bearing on undisturbed soil @ 1,500 psf</li> <li>✓ Per engineer report (comment or attach report)</li> </ul>				Formed & Reinforced Per City Approved Dwgs Garage structural slab per approved plan Basement slab on grade per approved plan 6 mil vapor barrier installed – not required for garage slab Isolation rings or block-outs are provided over pier pads for columns			
Cold weather protection				Footings			
✓ Wall fo ✓ Wall th ✓ Reinfor Hold do ✓ Wall op City app □ Deck/p ✓ Top of propos □ Max. 1: □ Ufer Gr (Give a	Wall forms centered on footings Wall thickness as specified on approved plans Reinforcement installed per approved plans Hold downs placed and installed properly Wall openings installed in accordance with City approved plans Deck/porch/balcony columns Top of wall and steps formed a minimum of 8" above proposed grading contours. Max. 12" block down at garage doors. Ufer Ground attachment rod left exposed (Give approx. location in comments)			Reinforced per city approved plans or engineer report  Deck/porch/balcony footings  Footing – width, depth and location per approved plans and, or engineer report  Solid jumps  Frost depth (min. 36 inches)  Column pads – basement  Column/pad at garage structural slab  Ufer Ground attachment rod provided  Illed Piers (refer to footings for deck piers)  Pier foundation per approved plan  Size:  Depth:  Bearing:			
clarify wh	nich walls are being						
Comment	ts:						
		our on the north wall. Forn			cement are		
direction, ins	tify that I, or qualified indivic spected and/ or tested the ab with the applicable City appro	pove checked items in			STEP TO		

approved plans and specifications.

Signed: Date:

codes and engineering details. The work is complete and to the best of my knowledge was found to be in substantial compliance with the  $\,$ 

02 AUG '24

