

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20242080

Address: 3725 SW KNOXVILLE CT, LEES SUMMIT, MO 64082  
3723 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Kyle Beard	Failed	Wednesday, August 28, 2024

Corrective Action Required:

1	Miscellaneous Correction	3723 and 3725 SW Knoxville rated assembly
		3723
		-Fire block Ibeam at demising wall in basement
		-Roof sheeting has a vent cut out in it within 4 feet of demising wall
		-Gaps in roof sheeting exceeds 1/4 of an inch
		-Remove wood wedges along the demising wall
		3725
		-Fire block Ibeam at demising wall in basement
		-Roof sheeting has a vent cut out in it within 4 feet of demising wall
		-Remove wood wedges along the demising wall

Comments: