



Third Party Inspection Report

Inspector	Date	T						
		Time						
David P. Ainsworth, P.E.	8-20-24	1100 PM						
Company	Permit #	Permit Holder						
David P. Ainsworth, P.E.								
Inspection Type	Address							
FOOTING	3716 \$ 3718 KNOXVILLE CT LSMO							
E Wall Address								
dainsworth@chelepis.com								
Instructions: This form must be completed when performing a third party inspection for any building								
permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services								
Department. If a subsequent inspection is performed by the City, this form must be submitted prior to that inspection being scheduled.								
Check all boxes that apply to the site conditions and the inspection being performed.								
Site Conditions:								
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)								
Erosion controls in place and maintained								
*Note: If these requirements are not m	et no inspection shall be performed	or accepted by the City.						
Foundations and Footings:								
Foundation type and MBOE is equal to or above the plot plan								
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)								
Foundation/Footing meets all City Code requirements and matches City approved plans or								
engineered design.		only approved plans of						
Foundation Walls:								
Elevation is sufficient to achieve	2% slope away from structure							
No openings below the MBOE								
Concrete encased electrode (uf	er) ground exposed							
Foundation wall meets all City Code requirements and matches City approved plans or engineered design.								



_		_					
-	r	aı	m	м	n	σ	•
•		ч.		ш		5	•

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

THERE IS AN UFER GROUND ROD IN EACH VINT OF THE DUPLEX. THEY ARE LOCATED IN THE REAR WALLS OF THE GARAGES. THEY ARE 91 FROM THE LEFT REAR CORNER AND 9' FROM RIGHT REAR CORNER AND 9' FROM

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both

accurate and true.

Signature: Said P. Answard P.

Engineer/Architect Seal