



---

**PUBLIC WORKS ENGINEERING DIVISION**

**Inspection Summary**

---

Permit #:PRPWRW20242220, Public Works Right of Way Permit  
Address: 4013 NE SAGAMORE DR, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Thad Nave	Passed	Tuesday, September 03, 2024

Corrective Action Required

1	Misc	Site visit, GF drop complete
---	------	------------------------------

**Comments:**