



# City of Lee's Summit Fire Department

Office of the Fire Marshal  
(816) 969-1300



## Sprinkler Flow Test Inspection Result

|   |  |
|---|--|
| <b>Inspected by</b><br>Robert D McQueen | <b>Completed at</b><br>10/15/2024 16:08:24 |
|---|--|

|  |                                 |                             |  |                     |
|--|---------------------------------|-----------------------------|--|---------------------|
| <b>Address</b><br>1950 SE BLUE<br>PKWY | <b>Suite</b><br>--              | <b>City</b><br>LEE'S SUMMIT | <b>State</b><br>MO                             | <b>Zip</b><br>64063 |
| <b>Business Name</b><br>--             | <b>Building Type</b><br>Unknown |                             | <b>Inspection Contact Name</b><br>Brad Lenheim |                     |

|   |
|---|
| <b>Inspection Number</b><br>LSFD-INS-2024-0001661 |
|---|

### Test:

**ITEM:** Company Doing Work

**RESULT:** American Fire Sprinkler

✓ Pass

**ITEM:** Fire Line Backflow/Current Cert. Test

✓ Pass

**ITEM:** Main Drain To Exterior or Compatible Drain

✓ Pass

**ITEM:** Spare Head Box Mounted With Heads and Wrench

✓ Pass

**ITEM:** Test Port Reduced to One Head Size

---

✓ Pass

**ITEM:** FDC Has Ball Drip Drain

---

✓ Pass

**ITEM:** Sprinkler Room Door Labeled

---

✓ Pass

**ITEM:** Pressurized Sys To OP Pressure (150 psi min)

---

✓ Pass

**ITEM:** FDC Operation

---

✓ Pass

**ITEM:** FDC Labeled/Area Of Protection

---

✓ Pass

**ITEM:** Fire Hydrant Operation

---

✓ Pass

**ITEM:** Fire Hydrant With In 100' of FDC

---

✓ Pass

**ITEM:** Water Flow Alarm (60 sec)

---

✓ Pass

**ITEM:** Riser Valves Labeled with Area of Protection

---

✓ Pass

**ITEM:** Hydraulic Specs On Riser

✓ Pass

**ITEM:** Current In-Service Tag On Riser

**Dry Sys:**

✓ Pass

**ITEM:** Air Pressure (dry & pre-action sys) Set At Least 20 psi Above Trip Pressure

✓ Pass

**ITEM:** Low Air Trip (60 sec)

✓ Pass

**ITEM:** Low Air Alarm

✓ Pass

**ITEM:** Water Flow At Test Port (60 sec)

**Pre-action Sys :**

N/A

**ITEM:** Pre-action Sys Tripped By Detection Sys - 1st Trip

N/A

**ITEM:** Pre-action Sys Tripped By Detection Sys - 2nd Trip

N/A

**ITEM:** Water Flow At Test Port (60 sec)

**Test Results:**

**ITEM:** Test Results

**RESULT:** Pass

# Inspection Signatures

Occupancy Contact Signature

Unable to sign:

Emailed photos of corrections from previous inspection

---

Brad Lenheim  
Contractor  
9139152219

blrnheim@americanfiresprinkler.com

Inspector Signature



---

Robert D McQueen  
Engineer

--