## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20231105 Address: 800 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Rated Ass	sembly Inspection	Robb Popp	Partial	Wednesday, October 16, 2024	
Informatio	onal:				
1	FIRST FLOOR	building A Complete			
		Building B: *Submit 3rd party approval for structural steel fireproofing			
		Building C: -complete			
		Building D: -complete			
Informatio	anal	Building E-1st layer behind tubs -RC at walls and ceilings except at garage 200 -1st and 2nd layer at firewalls -Screw pattern at walls and ceiling except at elevator, 220			
2	SECOND FLOOR	Building A: Complete			
		Building B:			

		-complete
	ional: FOURTH FLOOR	Building C: Complete
Corrective 3 Informati 4		Building D: Complete
		Building E: -RC at walls and ceiling -1st and 2nd layer at 2 hour walls -Screw pattern at walls and ceiling except at elevator
		Building A: Complete
		Building B: Copmlete
		Building C: Complete
		Building D: Complete
		Building E: -1st and 2nd layer behind tubs and showers -RC at units and corridors -1st layer screw pattern
		Building A: Complete
		Building B: -Complete
		Building C: Complete
		*Building D: Complete
		*Building E: -1st layer at truss space separation wall D/E -1st and 2nd Layer behind tubs -1st layer at firewalls -RC at units and corridors -Screw pattern at units and corridors except at elevator and firewall
Corrective 5	e Action Required: ELEVATOR 1	*Elevator 1 in building A

		-Complete				
Corrective	e Action Required:					
6	STAIR TOWER 1	*Stair A building A -Complete				
Informati	onal:					
7	STAIR TOWER 2	*Stair B in building B -Complete				
Informational:						
8	STAIR TOWER 3	Stair 2B in builidng B -Complete				
Informational:						
9	STAIR TOWER 4	*Stair D in building D -Complete				
Informational:						
10	STAIR TOWER 5	Stair E building E -Complete				
Informational:						
11	ELEVATOR 2	Elevator 2 in building C: -complete				
Corrective Action Required:						
12	ELEVATOR 3	Elevator 3 in building E -1st layer corridor side all floors -1st layer inside at corridor wall floors 1,2,4 -1st and 2nd layer at garage side -Unit side walls complete -Ceiling complete				

**Comments:**