

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20231105
Address: 800 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Robb Popp	Partial	Tuesday, October 22, 2024

Informational:

1 FIRST FLOOR

building A
Complete

Building B:
Complete

Building C:
-complete

Building D:
-complete

Building E-1st layer behind tubs
-RC at walls and ceilings except at garage 200
-1st and 2nd layer at firewalls
-Screw pattern at walls and ceiling except at, 220

Informational:

2 SECOND FLOOR

Building A:
Complete

Building B:

-complete

Building C:
Complete

Building D:
Complete

Building E:
Complete

Corrective Action Required:
3 THIRD FLOOR

Building A:
Complete

Building B:
Complete

Building C:
Complete

Building D:
Complete

Building E:
Complete

Informational:
4 FOURTH FLOOR

Building A:
Complete

Building B:
-Complete

Building C:
Complete

*Building D:
Complete

*Building E:
Complete

Corrective Action Required:
5 ELEVATOR 1

*Elevator 1 in building A
-Complete

Corrective Action Required:
6 STAIR TOWER 1

*Stair A building A
-Complete

Informational:
7 STAIR TOWER 2

*Stair B in building B
-Complete

Informational:

8 STAIR TOWER 3 Stair 2B in building B
-Complete

Informational:

9 STAIR TOWER 4 *Stair D in building D
-Complete

Informational:

10 STAIR TOWER 5 Stair E building E
-Complete

Informational:

11 ELEVATOR 2 Elevator 2 in building C:
-complete

Corrective Action Required:

12 ELEVATOR 3 Elevator 3 in building E
-1st and 2nd layer corridor side floors 1,2,4
-1st and 2nd layer inside at corridor wall floors 1,2,4
-1st and 2nd layer at garage side
-Unit side walls complete
-Ceiling complete

Comments: