## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20231204 Address: 2951 SE SHENANDOAH PKWY, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Khanh Nguyen	Failed	Wednesday, October 30, 2024
Corrective Action Required: 1 Misc	2-hr fire barrier wall, guest suite side-2nd layer installed, stairwell side screw pattern inspected		
	Elevator shaft wall-interior side layer screw pattern ok		
	<ul> <li>**Provide visual access to all floor and ceiling space around the elevator fire barrier enclosure; screw pattern was not inspected</li> <li>**Provide visual access to ceiling space of guest suite and floor below for inspection of the 2-hr fire barrier</li> </ul>		
		Provide visual access to verify fire-caulking of plumbing penetration behind andry wall; 2-hr protection around roof drainage above guest suite bathroom	

**Comments:**