

Third Party Inspection Report

Inspector	Date	Time								
PAVID P. AINSWORTH, PE	10-29-24	1:30 PM								
Company	Permit #	Permit Holder								
5 10										
DAVID P. AUNGWORTH, P.F.	2024-5176	CLAYTON PROPERTIE								
Inspection Type	2024-5176 Address HAWTHORN	-ot 187								
+OOTING	3219 SW AROR RID	GE CIRLSMO								
E-Mail Address										
dainsworth @ CHELEPIS Com										
Instructions: This form must be completed when performing a third party inspection for any building										
permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services										
Department. If a subsequent inspection is performed by the City, this form must be submitted prior to										
that inspection being scheduled.										
Check all boxes that apply to the site conditions and the inspection being performed.										
Site Conditions:										
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)										
Erosion controls in place and n	Erosion controls in place and maintained									
*Note: If these requirements are not n	Note: If these requirements are not met no inspection shall be performed or accepted by the City.									
Foundations and Footings:										
Foundation type and MBOE is equal to or above the plot plan										
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)										
Foundation/Footing meets all engineered design.	City Code requirements and matche	es City approved plans or								
Foundation Walls:										
Elevation is sufficient to achiev	e 2% slope away from structure									
No openings below the MBOE	,									
Concrete encased electrode (u	ifer) ground exposed									
Foundation wall meets all City engineered design.	Code requirements and matches Ci	ty approved plans or								



F	*	a	ľ	۲	i	n	g	*
•							-	

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER IS IN THE BACK WALL OF THE GARAGE B' DFF THE BACK RIGHT CORNER.

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both

accurate and true.

Engineer/Architect Seal

Signature: Navid P. answorth P.E.