CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Commercial		Robb Popp	Partial	Thursday, October 31, 2024	
Corrective Action Required:					
1	STAIR TOWER 1	Stair tower 1 in Building F: -Shear wall nailng pattern behind stringers at floors 1-3 *OK for first layer all floors inside of stairwell -1st layer all floors			
Corrective Action Required:					
2	STAIR TOWER 2	-Stair tower 2 in building -Shear wall nailing patter	G n behind stringers at floors	1-2	
Corrective Action Required:					
3	STAIR TOWER 3	-Stair tower 3 in building	J n behind stringers floors 1-:	2	
Correctiv	e Action Required:	-Shear wan naning patter	ii benniu stringers noors 1-	5	
4 FIRST FLOOR		Building F Complete except as noted: 157-NOT READY 389-Walls only ok-complete meps at ceiling and seal dead space			
		Building G: -Behind tubs and showers			
		Building J:			
		-Balconies ok to cover			

Corrective Action Required: 5 SECOND FLOOR	Building F: Complete except as noted: 237-Protect nm at island
	Building G: -Behind tubs and showers for pre rock
	Building J: -Balconies ok to cover
Corrective Action Required: 6 THIRD FLOOR	*Building F -Units and corridor approved except as noted: 349-Install (3) stud shoe at corridor
	Building G: -Behind tubs and showers for pre rock
Corrective Action Dequired	Building J: -Balconies ok to cover
Corrective Action Required: 7 FOURTH FLOOR	*Building F -Behind tubs and showers ok to cover -Deck framing ok to cover -Units and corridor approved
	*Building G: -Behind tubs and showers ok
	*Building J -Behind tubs and showers ok to cover
	Building J: -Balconies ok to cover
Corrective Action Required: 8 ELEVATOR 1	Interior framing ok all floors

Comments: