

chris@shedigsit.com

Report Email:

Copy Email:

Lab Report Fax No:

Lab Report Contact 1: (816) 564-6087

Lab Report Contact 2:

Chris Rimel

She Digs It

600 SE Central Drive

Customer ID No: 8930

Customer PO No:

Collected By: Client

Invoice No: 62210

Blue Springs, MO 64014

## Report of Analysis

Laboratory Report ID No:

**20541**

**Project Name:** MCC Longview Automotive Institute

Item No.	Cat NO	ANALYSIS	COLLECTED	ANALYZED	REPORTING	LIMIT	RESULTS
	Line NO	SAMPLE TYPE	SAMPLE SITE NOTES		TEST METHOD		
1	6191	Bacteria, P/A E. Coli	10/29/24	10/30/24	1	CFU/100mL	Negative
	137736		Private service Line sample 1		SM9223 B		CFU/100mL
2	6191	Bacteria, P/A E. Coli	10/29/24	10/30/24	1	CFU/100mL	Negative
	137737		Private Fire Line Sample 1		SM9223 B		CFU/100mL
3	6190	Bacteria, P/A T. Coliform	10/29/24	10/30/24	1	CFU/100mL	Negative
	137735		Private service Line sample 1		SM9223 B		CFU/100mL
4	6190	Bacteria, P/A T. Coliform	10/29/24	10/30/24	1	CFU/100mL	Negative
	137738		Private Fire Line Sample 1		SM9223 B		CFU/100mL
5	6191	Bacteria, P/A E. Coli	10/29/24	10/30/24	1	CFU/100mL	Negative
	137734	Grab	6" private fire hydrant line #3		SM9223 B		CFU/100mL
6	6190	Bacteria, P/A T. Coliform	10/29/24	10/30/24	1	CFU/100mL	Negative
	137733	Grab	6" private fire hydrant line #3		SM9223 B		CFU/100mL

**Comments, if present, concern this Lab Work Order:**

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without written approval by Blue Valley Laboratories, Inc.