

chris@shedigsit.com

Report Email:

Copy Email:

Lab Report Fax No:

Lab Report Contact 1: (816) 564-6087

Lab Report Contact 2:

Chris Rimel

She Digs It

600 SE Central Drive

Customer ID No: 8930

Customer PO No:

Collected By: Client

Invoice No: 62214

Blue Springs, MO 64014

Report of Analysis

Laboratory Report ID No:

20544

Project Name: MCC Longview Automotive Institute

Item No.	Cat NO	ANALYSIS	COLLECTED	ANALYZED	REPORTING	LIMIT	RESULTS
	Line NO	SAMPLE TYPE	SAMPLE SITE NOTES		TEST METHOD		
1	6191	Bacteria, P/A E. Coli	10/30/24	10/31/24	1	CFU/100mL	Negative CFU/100mL
	137753		Private service Line sample 2		SM9223 B		
2	6191	Bacteria, P/A E. Coli	10/30/24	10/31/24	1	CFU/100mL	Negative CFU/100mL
	137754		Private Fire Line Sample 2		SM9223 B		
3	6190	Bacteria, P/A T. Coliform	10/30/24	10/31/24	1	CFU/100mL	Negative CFU/100mL
	137752		Private service Line sample 2		SM9223 B		
4	6190	Bacteria, P/A T. Coliform	10/30/24	10/31/24	1	CFU/100mL	Negative CFU/100mL
	137755		Private Fire Line Sample 2		SM9223 B		
5	6191	Bacteria, P/A E. Coli	10/30/24	10/31/24	1	CFU/100mL	Negative CFU/100mL
	137751	Grab	6" private fire hydrant line #4		SM9223 B		
6	6190	Bacteria, P/A T. Coliform	10/30/24	10/31/24	1	CFU/100mL	Negative CFU/100mL
	137750	Grab	6" private fire hydrant line #4		SM9223 B		

Comments, if present, concern this Lab Work Order:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without written approval by Blue Valley Laboratories, Inc.