

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20245356, Public Works Right of Way Permit Address: 3301 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Site Visit Inspection Matt Munger Partial Wednesday, November 06,

2024

Corrective Action Required

1 Misc Site Visit- there is locate paint marks on the ground, no workers

present. Monitoring.

Comments: