## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20243548

Address: 1233 NE GOSHEN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Wednesday,

Residential November 06, 2024

Corrective Action Required:

1 Misc -Fb duct chase from joist space

-Engineer to address notched (2)2x12 beam above master closet

-Nail window king studs to headers \*\* near master bedroom corner; at

kitchen sink

-The (3)2x10 beam at stair is notched. Have engineer address this \*\*There's

no footing under the wall. Your engineer must address this

\*\*OK TO INSULATE

**Comments:**