

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20240346  
Address: 2783 SW 11TH TER, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection - Codes Residential</b>	Shawn Hoffman	Failed	Friday, November 15, 2024

Corrective Action Required:

- |   |      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
|---|------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1 | Misc | <ul style="list-style-type: none"><li>- Fire block ceiling penetrations at garage</li><li>- Provide handrail for garage entry stairs</li><li>- Provide attic access cover</li><li>- Door att garage entry to be self closing and latch</li><li>- Provide graspable handrail for deck stairs</li><li>- Completed hardware at front door</li><li>- Provide security screws at back door</li><li>- Missing anti siphon device at spigot at main water shut off</li><li>- Provide temper resistant caps at AC compressor</li><li>- Missing splash pads at down spouts</li></ul> |
|---|------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

**Comments:**