

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20240880
Address: 1836 SW SAGE CANYON RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Kyle Beard	Failed	Wednesday, December 04, 2024

Corrective Action Required:

1	Miscellaneous Correction	1836 SW Sage Canyon. Occupancy Install spark rings in kitchen backsplash at light/receptacle and down stairs kitchenette backsplash receptacles Fire block gaps in sheet rock in garage above overhead garage doors Bedroom escape window well has a greater than 44 inch wall and requires a escape ladder Back of house sod is in contact with the exterior wall siding
---	-----------------------------	---

Comments: