

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242945

Address: 3718 SW KNOXVILLE CT, LEES SUMMIT, MO 640823716 SW KNOXVILLE CT, LEES SUMMIT, MO
64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Shawn Hoffman	Failed	Friday, December 06, 2024

Corrective Action Required:

1 Misc

16

- Repair sheet rock garage demise wall
- More Screws needed at basement bedroom
- No rock behind shower enclosure at basement
- No sheet rock behind second floor shower

18

- No rock behind shower enclosure at basement
- No sheet rock behind second floor shower
- Screw off sill plate garage Denise wall

Comments: