

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20242763

Address: 3713 SW KNOXVILLE CT, LEES SUMMIT, MO 64082  
3711 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Kyle Beard	Failed	Monday, December 30, 2024

Corrective Action Required:

1	Miscellaneous Correction	3713 Seal around bonding wire at demising wall Seal all the way around service cable at demising wall Provide UL listing for green board used in bedroom 1 and above bedroom 1 There is a gap in the demising wall above bedroom 1's ceiling behind a vertical 2x4
		3711 Seal all the way around service cable at demising wall Provide UL listing for green board used in bedroom 1 and above bedroom 1 Demising wall does not meet at the west wall in attic space above bedroom 1

**Comments:**