CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20243123

Address: 3719 SW KNOXVILLE CT, LEES SUMMIT, MO 640823717 SW KNOXVILLE CT, LEES SUMMIT, MO

64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Kyle Beard Failed Tuesday, December

Residential 31, 2024

Corrective Action Required:

2 Miscellaneous 3717

Correction Have engineers letter for garage bottom plate not being fully supported by

the foundation wall and proper tie down recommendation (see engineers

report on size of all thread bolt into concrete stem wall)

Newly installed 5/8 inch anchor bolts have broken out the foundation wall.

Have engineers report on a repair

3719

Floor joist above ceiling by entry closet in garage raceway has been over notched for 2 in plumbing DWV (have engineers report off a repair)

Trap weir to vent in utility room are not to code (P3105.3)

Comments: