

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242763

Address: 3713 SW KNOXVILLE CT, LEES SUMMIT, MO 64082
3711 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|----------------------------------|------------|----------|----------------------------|
| Rated Assembly Inspection | Kyle Beard | Failed | Thursday, January 02, 2025 |

Corrective Action Required:

| | | |
|---|--------------------------|------|
| 1 | Miscellaneous Correction | 3713 |
|---|--------------------------|------|

Provide UL listing for green board used in bedroom 1 and above bedroom 1
There is a gap in the demising wall above bedroom 1's ceiling behind a vertical 2x4

3711

Provide UL listing for green board used in bedroom 1 and above bedroom 1
Demising wall does not meet at the west wall in attic space above bedroom 1

Comments: