CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20243123 Address: 3719 SW KNOXVILLE CT, LEES SUMMIT, MO 640823717 SW KNOXVILLE CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Residential		Kyle Beard	Passed	Friday, January 17, 2025
Corrective 1	Action Required: Miscellaneous Correction	the foundation wall an report on size of all thr Newly installed 5/8 inc Have engineers report 3719 Floor joist above ceilin notched for 2 in plumb	ve engineers letter for garage bottom plate not being fully supported by foundation wall and proper tie down recommendation (see engineers port on size of all thread bolt into concrete stem wall) wly installed 5/8 inch anchor bolts have broken out the foundation wall. ve engineers report on a repair	
				、 <i>·</i>

Comments: