CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20242123Address:2508 NE WOODLAND OAK CIR, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
All Rough Inspection - Residential	Khanh Nguyen	Failed	Tuesday, January 28, 2025	
Corrective Action Require	ed:			
1 Misc	-Nail front ZIP sheathing **The ZIP board outside the front office is not nailed properly (8d@12" in field)			
	•	-Engineer address support for ridge and hips above loft **The plan does not show the vault connection detail that it refers to on the same sheet		
	-Missing IvI beam und wall? Verify	-Missing IvI beam under kitchen **Is there an LVL beam under the bearing wall? Verify		
	**OK TO INSULATE			

Comments: