CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242763

Address: 3713 SW KNOXVILLE CT, LEES SUMMIT, MO 640823711 SW KNOXVILLE CT, LEES SUMMIT, MO

64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Kyle Beard Failed Wednesday, January Residential 29, 2025

Corrective Action Required:

2 Miscellaneous

3711

Correction

- Strap top plate in bathroom 1 at plumbing vent line where it is bored more

than 50 percent at exterior wall

3713

- Strap top plate at bathroom 1 @ DWV of load bearing exterior

Walk your property before scheduling your inspections

10:09am. KBEARD

Comments: