CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20235733 Address: 209 SE GREEN ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial		Robb Popp	Partial	Tuesday, February 04, 2025
Informational:				
1 Misc -Conduit from mech r -Communication cond -Conduit for (4) recep -Conduit for (4) recep -Conduit from SE side clocktower -Christmas tree run at west side of building -Ground ring with (3) disconnect - West side wicket ins -East side wickets and -East wicket, Ballard a -Electrical street light Cooper -East side of Green street - Cooper		-Conduit for (4) receptacl -Conduit from SE sidewal clocktower -Christmas tree run at SE west side of building -Ground ring with (3) grou disconnect - West side wicket inspec -East side wickets and bal -East wicket, Ballard and bal - Electrical street lighting Cooper -East side of Green street	from 118 to line 5 (108 mec es at SW corner of City Hall k to NE corner and East to co corner of city hall to quaysio und rods at transformer loca tion passed and is okay to co llard lighting holiday lighting conduit west side of Johnso	ourtyard stairs and de box roughly 15' from ation for service cover on street south of

Comments: