

Third Party Inspection Report

Inspector	Date	Time								
AL HERMANS	2/4/25	12:00 pm								
Company	Permit #	Permit Holder								
SDC ENGINEERING	PRNES 2024 6296	Permit Holder WACKER CUSTOM HOMES								
Inspection Type	Address	*								
40017NG	2531 NE WOODL	AND OAKS CIRCL								
E-Mail Address alhermans@Sdc-corp-com										
Instructions: This form must be completed when performing a third party inspection for any building										
permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services										
Department. If a subsequent inspection is performed by the City, this form must be submitted prior to that inspection being scheduled.										
Check all boxes that apply to the site conditions and the inspection being performed.										
Site Conditions:										
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)										
Erosion controls in place and maintained										
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.										
Foundations and Footings:										
Foundation type and MBOE is equal to or above the plot plan										
Concrete encased electrode (u	Concrete encased electrode (ufer) ground installed (Location must be noted in comments)									
Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.										
Foundation Walls:										
Elevation is sufficient to achiev	e 2% slope away from structure									
No openings below the MBOE										
Concrete encased electrode (u	Concrete encased electrode (ufer) ground exposed									
Foundation wall meets all City engineered design.	Foundation wall meets all City Code requirements and matches City approved plans or engineered design.									



_										
⊢	r	2	1	Y	٦	1	1	٦	σ	
		a	ı		1	•	1	1	ร	

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

ZUFERS ±3' REAR OF LEFT FRONT CORNER ±3' REAR OF RIGHT REAR GARAGE CORNER

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature: Engineer/Architect Seal