



Special Inspection Daily Report

Report #: SIR-000003
Report Date: 10/23/2024

Olathe
1700 East 123rd Street
Olathe, KS 66061
Phone: 913-829-0078
Fax: 913-829-0258

Client:
City of Lee's Summit MO
Accounts Payable
220 SE Green St
Lees Summit, MO 64063-2706

Project:
L22-05531
LSMO Water Utilities Facility Canopies
1200 Southeast Hamblen Road
Lee's Summit, MO

General Information

Project Phase: Special Inspections

Technician: Menchaca, Ivan

Date: 10/10/2024

Arrival Time: 13:00

Temperature (°F): 83

Weather: Sunny

Departure Time: 15:35

Work Completed

Inspection Item: Reinforced Concrete

Location: 4 bases on the South East corner

Frequency: Periodic

Tests Performed:

Slump, temperature, unit weight and air
concrete testing and visual.

Work Completed Description:

As requested, Olsson arrived on site to inspect the reinforced steel and perform concrete testing on the 4 bases on the south east corner.

Test results and observations appeared to meet project specifications and results were shared with contractor.

Determination

☐ Discrepancy Noted ☒ As Specified ☐ Not Applicable

Olathe
1700 East 123rd Street
Olathe, KS 66061
Phone: 913-829-0078
Fax: 913-829-0258

Client:
City of Lee's Summit MO
Accounts Payable
220 SE Green St
Lees Summit, MO 64063-2706

Project:
L22-05531
LSMO Water Utilities Facility Canopies
1200 Southeast Hamblen Road
Lee's Summit, MO



Image Description: NW base




Image Description: NE base



Image Description: SE base



Image Description: SW base



Special Inspection Daily Report

Report #: SIR-000003
Report Date: 10/23/2024

Olathe
1700 East 123rd Street
Olathe, KS 66061
Phone: 913-829-0078
Fax: 913-829-0258

Client:
City of Lee's Summit MO
Accounts Payable
220 SE Green St
Lees Summit, MO 64063-2706

Project:
L22-05531
LSMO Water Utilities Facility Canopies
1200 Southeast Hamblen Road
Lee's Summit, MO


Christy Wilson
Project Engineer
10/23/2024
