



**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #:PRPWRW20250287, Public Works Right of Way Permit

Address: 366 NW PATCH CT, LEES SUMMIT, MO 640812113 NW OBRIEN RD, LEES SUMMIT, MO 640812091 NW OBRIEN RD, LEES SUMMIT, MO 640812225 NW KILLARNEY LN, LEES SUMMIT, MO 64081377 NW PATCH CT, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Site Visit Inspection</b>	Matt Munger	Partial	Tuesday, February 25, 2025

**Corrective Action Required**

1	Misc	Site Visit - It appears the install work has been completed. There is a core hole at NW Patch Ct. And NW Obrien that will need to be properly filled in.
---	------	--

**Comments:**