

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #:PRPWRW20232072, Public Works Right of Way Permit Address: 3824 SW WALSH DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

**Site Visit Inspection** Matt Munger Passed Monday, March 10, 2025

Corrective Action Required

1 Misc Closing.

Comments: