

Third Party Inspection Report

Inspector	Date	Time	
David P. Ainsworth, P.E.	3-10-25	12:10 Pm	
Company	Permit #	Permit Holder	
David P. Ainsworth, P.E.	2025-0504	A PLACE CALLED HOW	
Inspection Type	Address PARKRIPHE LOT 368		
FOOTING	4331 NE HIDEAWAY DR LSMO		
E-Mail Address dainsworth@chelepis.com			
Instructions: This form must be completed when performing a third party inspection for any building permit in Lee's Summit. Submit form within 48 hours after inspection to the Development Services Department. If a subsequent inspection is performed by the City, this form must be submitted prior to that inspection being scheduled.			
Check all boxes that apply to the site conditions and the inspection being performed.			
Site Conditions:			
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)			
Erosion controls in place and maintained			
*Note: If these requirements are not met no inspection shall be performed or accepted by the City.			
Foundations and Footings:			
Foundation type and MBOE is equal to or above the plot plan			
Concrete encased electrode (ufer) ground installed (Location must be noted in comments)			
Foundation/Footing meets all City Code requirements and matches City approved plans or engineered design.			
Foundation Walls:			
Elevation is sufficient to achie	Elevation is sufficient to achieve 2% slope away from structure		
No openings below the MBOE	No openings below the MBOE		

Foundation wall meets all City Code requirements and matches City approved plans or

Concrete encased electrode (ufer) ground exposed

engineered design.