

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20231204  
Address: 2951 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Khanh Nguyen	Partial	Friday, March 14, 2025

Corrective Action Required:

1	Misc	2-hr fire barrier: -guest suite side and stairwell side-2nd layer -wall inside lower level bathroom and storage space under guest rm-2nd layer  Elevator shaft wall: -interior side-side and back walls only -outer side-basement floor front wall  **Repatch holes in rated ceiling above bathroom and storage to UL design compliance-2nd layer above channels ok. Mud and tape patch  **Elevator fire barrier enclosure: outer side screw pattern was not inspected **Provide visual access to verify fire-caulking of plumbing penetration behind laundry wall; 2-hr protection around roof drainage above guest suite bathroom
---	------	--

Comments: