

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #:PRPWRW20250814, Public Works Right of Way Permit
Address: 402 SW 3RD ST, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|------------------------------|-------------|----------|-------------------------|
| Site Visit Inspection | Matt Munger | Partial | Tuesday, March 18, 2025 |

Corrective Action Required
1 Misc AM Site Visit - 8:22 a.m. no workers were onsite. Steel plates are down and the excavator is on top securing the plates. MM.

| | | | |
|------------------------------|-------------|---------|-------------------------|
| Site Visit Inspection | Matt Munger | Partial | Tuesday, March 18, 2025 |
|------------------------------|-------------|---------|-------------------------|

Corrective Action Required
1 Misc AM Site Visit - 10:00 a.m. A crew was pulling cable from the man hole west of where the damage was dug to fix the duct bank. No one was working at the excavation site and the plates and excavator were still in place. I asked the worker onsite if they had fixed the duct bank he said he wasn't sure.

Comments: