

Third Party Inspection Report

Inspector	Date	Time									
David P. Ainsworth, P.E.	5-7-25	2:30 Pm									
Company	Permit #	Permit Holder									
David P. Ainsworth, P.E.	2025-1603	CLAYTON PROPERTE									
Inspection Type	Address WOODSIDE RIDE	58 Lot 152									
	Pection Type Address WOODSIDE RIDGE LOT 152 ZOGO NW 6 RPIEN RD LSM6										
E-Mail Address dainsworth@chelepis.co											
Instructions: This form must be co	mpleted when performing a third p	arty inspection for any building									
permit in Lee's Summit. Submit form	within 48 hours after inspection to	the Development Services									
Department. If a subsequent inspection that inspection being scheduled.	on is performed by the City, this for	m must be submitted prior to									
Check all boxes that apply to the site of	onditions and the inspection being	performed.									
Site Conditions:											
Plans stamped by the City on site with the plot plan included. (Copied plans are not acceptable)											
Erosion controls in place and r	naintained										
*Note: If these requirements are not n	net no inspection shall be performe	d or accepted by the City.									
Foundations and Footings:											
Foundation type and MBOE is	equal to or above the plot plan										
Concrete encased electrode (u	fer) ground installed (Location mus	t be noted in comments)									
Foundation/Footing meets all engineered design.	City Code requirements and matche	es City approved plans or									
Foundation Walls:											
Elevation is sufficient to achiev	e 2% slope away from structure										
No openings below the MBOE											
Concrete encased electrode (L	fer) ground exposed										
Foundation wall meets all City engineered design.	Code requirements and matches Ci	ty approved plans or									



_						•				
⊦	r	a	r	Y	١	ı	r	١	σ	•
•		u			ı	ŧ	ı	•	5	•

Framing meets all City Code requirements and matches City approved plans or engineered design.

*Note: Framing can only be covered after mechanical, electrical, and plumbing inspections have been passed.

Corrective Actions and Comments:

UFER IS IN BACK OF 3 PD CAR GARAGE 2' OFF THE BACK RIGHT CORNER

I certify that I have inspected, tested, and checked the work performed, and I find the work to be compliant with all applicable City ordinances and approved building plans and site plans and that the all information in this form is both accurate and true.

Signature:

and Unsual Engineer/Architect Seal