

Alpha Omega Geotech, Inc 1701 State Avenue Kansas City, KS 66102 Phone: 913-371-0000

## **Proofroll Inspection**

Client:

Project:

Ward Development 1120 NW Eagle Ridge Blvd Grain Valley, MO 64029 230529 Lakewood Business Center Lot 1 NE Maguire Blvd Lee's Summit, MO 64064

Date: 09/11/2024 Inspector: Zaii Graves

Temperature (F): 89 Weather: Sunny

## **OBSERVATIONS**

**Location:** West, North, East parking lots. **Equipment Used:** 

Tandem axel dump truck. Approximately 13-14 tons

Description Of Subgrade: Light brown Acceptance of Subgrade: Yes

Remarks: No rutting was observed. Minimal pumping was observed but none that broke the surface

Jeff Mayer

Reviewed by: Jeff Marquez

09/25/2024