

Stormwater Pollution Prevention Plan Inspection Report

Project Name and Location: Blackwell

Weather: 67				
		□Clo	oudy $oxtimes$ Sunny $oxtimes$ Rain $oxtimes$ Snowing/ Snow cover	
Date of inspection: 5/19/25				
Inspectors Name: Jessica Ekster				
Type of Inspection: $oximes$ Regular $oximes$ Rain event $oximes$ Other:				
Rain in last 24 hrs (inches): NA				
Owner/Permittee: Griffin Riley				
Current Site Condition: Active				
			_	
BMP Checklist	Yes	<u>No</u>	Current Construction/Active Areas:	
Inlet Barriers	<u>N</u>		Vertical	
Sediment Barriers	\boxtimes			
Construction Entrance	\boxtimes			
Stream Crossings		\boxtimes		
Seed/Sod/Hydroseed/Mulch/Blanket		\boxtimes		
Sediment Basins & Discharge Locations		<u> </u>		
Borrow Areas		\boxtimes		
General Site Conditions		<u>N</u>		
Concrete Washout	☒			

Problem Areas/Special Observations (Note problem areas ONLY below):

ВМР	Location	Observation, Effectiveness, & Corrective Actions Ordered
Silt fence	Along curb	Repair a few areas where the fence has been damaged or un-trenched
Stabilize	In-active	Stabilize all areas that have been inactive for 14+ days- Weeds are not considered vegetation.
Stabilize	Swale	Stabilize swale on North end as soon as possible if work is done
Stabilize	Detention Ponds	Stabilize detention ponds asap- weeds are not considered vegetation
Streets	Throughout Site	Clean streets
Silt fence	Perimeter	Orange silt fence is not trenched in on East side of pond behind
		Residences- See picture below and noted on map

Have items noted on the last inspection been corrected? \square Yes \bowtie No (if no explain): Need to stabilize in-active areas and det. ponds.

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 7 days, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

Signature: (



