
Report Of: Proofroll Observation

Lab No: 17199-3

Report No: C24T2055-0101

Project No: C24T2055

Client: CTYSCACO

Page 1 of 1

Client: Cityscape Construction - Tudor, LLC
Tom Vernizzi
10 W Carmel Dr
Ste 200
Carmel, IN 46032

Project: Evren Apartments - Lee's Summit, MO

Report Date: 05/23/2025

Service Date: 05/22/2025

Technician: Bucl, Colby

Client PO:

Location: 25 NE Tudor Rd, Lee's Summit, MO 64086

Kaw Valley Engineering (KVE) was on site to observe a proofroll test performed by the Contractor.

Location: Parking lot and roadway north of the Clubhouse building.

The proofroll was performed with: a tandem truck with a gross weight of 32.68 tons.


Our representative observed a proofroll of the material at the location listed above.

Based on our observations as described above, the materials and procedures at the time of our site visit were in general conformance with the construction documents.

On-site personnel were verbally informed of the observations and test results.

Orig: Cityscape Construction - Tudor, LLC
Attn: Tom Vernizzi (1-ec copy)
1-ec Cityscape Residential, LLC Attn: Tim Mertz
1-ec Cityscape Construction - Tudor, LLC
Attn: Shawn Bartholomew
1-ec Cityscape Construction - Tudor, LLC
Attn: Lyndsey Diffey

Respectfully Submitted,
Kaw Valley Engineering



Glenn Schouten, Materials Engineer