

**Report Of: Field Density Testing Observations**

**Lab No: 16089-2**

**Report No: C24T2055-0050**

**Project No: C24T2055**

**Client: CTYSCACO**

**Page 1 of 1**

**Client:** Cityscape Construction - Tudor, LLC  
Tom Vernizzi  
10 W Carmel Dr  
Ste 200  
Carmel, IN 46032

**Project:** Evren Apartments - Lee's Summit, MO

**Report Date:** 04/23/2025

**Service Date:** 04/22/2025

**Technician:** Spurgeon, Patrick

**Client PO:**

**Location:** 25 NE Tudor Rd, Lee's Summit, MO 64086

Kaw Valley Engineering (KVE) was on site to perform in-place density tests on soil and/or aggregate materials.

Material: Brown/Dark Brown Clay


Our representative performed in-place moisture and density tests using a nuclear density gauge. Test results are presented on the attached sheet(s).

Based on our observations as described above, the materials and procedures at the time of our site visit were in general conformance with the construction documents.

On-site personnel were verbally informed of the observations and test results.

Orig: Cityscape Construction - Tudor, LLC  
Attn: Tom Vernizzi (1-ec copy)  
1-ec Cityscape Residential, LLC Attn: Tim Mertz  
1-ec Cityscape Construction - Tudor, LLC  
Attn: Shawn Bartholomew  
1-ec Cityscape Construction - Tudor, LLC  
Attn: Lyndsey Diffey

Respectfully Submitted,  
Kaw Valley Engineering



Glenn Schouten, Materials Engineer