

Report Of: Field Density Testing Observations

Lab No: 15585-2

Report No: C24T2055-0026

Project No: C24T2055

Client: CTYSCACO

Page 1 of 1

Client: Cityscape Construction - Tudor, LLC
Tom Vernizzi
10 W Carmel Dr
Ste 200
Carmel, IN 46032

Project: Evren Apartments - Lee's Summit, MO

Report Date: 04/04/2025

Service Date: 04/04/2025

Technician: Spurgeon, Patrick

Client PO:

Location: 25 NE Tudor Rd, Lee's Summit, MO 64086

Kaw Valley Engineering (KVE) was on site to perform in-place density tests on soil and/or aggregate materials.

Material: Brown/Dark Brown Clay


Our representative performed in-place moisture and density tests using a nuclear density gauge. Test results are presented on the attached sheet(s).

Based on our observations as described above, the materials and procedures at the time of our site visit were in general conformance with the construction documents.

On-site personnel were verbally informed of the observations and test results.

Orig: Cityscape Construction - Tudor, LLC
Attn: Tom Vernizzi (1-ec copy)
1-ec Cityscape Residential, LLC Attn: Tim Mertz
1-ec Cityscape Construction - Tudor, LLC
Attn: Shawn Bartholomew
1-ec Cityscape Construction - Tudor, LLC
Attn: Lyndsey Diffey

Respectfully Submitted,
Kaw Valley Engineering



Glenn Schouten, Materials Engineer