

Report Of: Proofroll Observation		Lab No: 15444-1	
		Report No: C24T2055-0021	
Project No: C24T2055 Client:	CTYSCACO		Page 1 of 1
Client: Cityscape Construction - Tudor, LLC Tom Vernizzi		Project: Evren Apartments - Lee's Summit, MO	
10 W Carmel Dr Ste 200		Report Date:	04/03/2025
Carmel, IN 46032		Service Date:	03/29/2025
Location:25 NE Tudor Rd, Lee's Summit, MO 64086		Technician:	Spurgeon, Patrick
		Client PO:	

Kaw Valley Engineering (KVE) was on site to observe a proofroll test performed by the Contractor.

Location: W. End of Site, just S. of Job trailer, and site of future Clubhouse for Evren Apartments.

The proofroll was performed with: Loaded 33,000lb water truck

Our representative observed a proofroll of the material at the location listed above.

Based on our observations as described above, the materials and procedures at the time of our site visit were in general conformance with the construction documents.

On-site personnel were verbally informed of the observations and test results.

Orig: Cityscape Construction - Tudor, LLC Attn: Tom Vernizzi (1-ec copy) 1-ec Cityscape Residential, LLC Attn: Tim Mertz 1-ec Cityscape Construction - Tudor, LLC Attn: Shawn Bartholomew 1-ec Cityscape Construction - Tudor, LLC Attn: Lyndsey Diffey

Respectfully Submitted, Kaw Valley Engineering

Glenn Schouten, Materials Engineer

THIS REPORT APPLIES ONLY TO THE STANDARDS OR PROCEDURES INDICATED AND TO THE SAMPLE(S) TESTED AND/OR OBSERVED AND ARE NOT NECESSARILY INDICATIVE OF THE QUALITIES OF APPARENTLY IDENTICAL OR SIMILAR PRODUCTS OR PROCEDURES, NOR DO THEY REPRESENT AN ONGOING QUALITY ASSURANCE PROGRAM UNLESS SO NOTED. THESE REPORTS ARE FOR THE EXCLUSIVE USE OF THE ADDRESSED CLIENT AND ARE NOT TO BE REPRODUCED WITHOUT WRITTEN PERMISSION.