CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20235208 Address: 2911 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Khanh Nguyen	Partial	Thursday, June 05, 2025
Corrective Action Required:1LOWER LEVELCorrective Action Required:2FIRST FLOORCorrective Action Required:3SECOND FLOORCorrective Action Required:4THIRD FLOOR	-Tub&shower walls-pre-roo	ск ОК	
Corrective Action Required: 5 STAIR TOWER 1	 **THIS IS NORTH STAIR A* Lower floor: -stair side 2nd layer 1st floor: -stair side 2nd layer 	ew GB to bottom wall plates *	
	2nd floor:		

		-stair side 2nd layer
		3rd floor: -stair side 2nd layer
Corrective 6	Action Required: STAIR TOWER 2	**THIS IS SOUTH STAIR A**
		Lower floor: -stair side 2nd layer
		1st floor: -stair side 2nd layer
		2nd floor: -stair side 2nd layer
		3rd floor: -stair side 2nd layer
Corrective	Action Required:	
7	STAIR TOWER 3	**THIS IS REAR STAIR B**
		Lower floor: -elevator/stair wall-stair side 2nd layer
8	Action Required: ELEVATOR 1 Action Required:	
4	FOURTH FLOOR	-Tub&shower walls-pre-rock OK
		**Corrections:

-Kitchen/corridor walls-screw GB to bottom wall plates

Comments: