

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245515
Address: 2624 NE WOODLAND OAK DR, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Monday, June 16, 2025

Corrective Action Required:

- | | | |
|---|------|---|
| 1 | Misc | <ul style="list-style-type: none">-Flashing above horizontal trims at front-Provide double trimmer joists adjacent to attic access opening located more than 3 ft from support-Support lvl hip above kitchen, hip rafter above rear patio/living rm area, and master bedroom per plan-Fasten blockings behind d straps to 2x12 header at rear CSPF walls-Fb fireplace wall space from roof-Install beam and support bottom of hip rafter above front bathroom to beam-Nail hanger above bottom stair light switch-Fb floor at tub trap above bedroom 5 |
|---|------|---|

**OK TO INSULATE

Comments: