

Dave

Report Email: davejr@beemerconstruction.

Copy Email:

Lab Report Fax No: (816) 229-2571

Lab Report Contact 1: (816) 229-2266

Lab Report Contact 2: (816) 985-6305

Customer ID No: 7931

Customer PO No: chadj@beemerconstruc

Collected By: Client

Invoice No: 64274

Beemer Construction

606 SE Central

Blue Springs, MO 64014

Report of Analysis

Laboratory Report ID No:

20892

Project Name: K & R Wholesale Newberry Landing (1460 SE Broadway)

Item No.	Cat NO	ANALYSIS	COLLECTED	ANALYZED	REPORTING LIMIT	RESULTS
	Line NO	SAMPLE TYPE	SAMPLE SITE NOTES		TEST METHOD	
1	6191	Bacteria, P/A E. Coli	6/24/25	6/25/25	1 CFU/100mL	Negative CFU/100mL
	140893	Grab	Spot 1 Sample 7		SM9223 B	
2	6190	Bacteria, P/A T. Coliform	6/24/25	6/25/25	1 CFU/100mL	Negative CFU/100mL
	140894	Grab	Spot 1 Sample 7		SM9223 B	

Comments, if present, concern this Lab Work Order:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without written approval by Blue Valley Laboratories, Inc.