

Dave

Report Email: davejr@beemerconstruction.

Copy Email:

Lab Report Fax No: (816) 229-2571

Lab Report Contact 1: (816) 229-2266

Lab Report Contact 2: (816) 985-6305

Customer ID No: 7931

Customer PO No:

Collected By: Client

Invoice No: 64267

Beemer Construction

606 SE Central

Blue Springs, MO 64014

Report of Analysis

Laboratory Report ID No:

20886**Project Name:** K & R Wholesale Newberry Landing (1460 SE Broadway)

Item No.	Cat NO	ANALYSIS	COLLECTED	ANALYZED	REPORTING	LIMIT	RESULTS
	Line NO	SAMPLE TYPE	SAMPLE SITE NOTES		TEST METHOD		
1	6191	Bacteria, P/A E. Coli	6/23/25	6/24/25	1	CFU/100mL	Negative CFU/100mL
	140774	Grab	Spot 1 Sample 6		SM9223 B		
2	6190	Bacteria, P/A T. Coliform	6/23/25	6/24/25	1	CFU/100mL	Negative CFU/100mL
	140871	Grab	Spot 1 Sample 6		SM9223 B		

Comments, if present, concern this Lab Work Order:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without written approval by Blue Valley Laboratories, Inc.