



Backflow Prevention Assembly Test Data & Maintenance Report

ACCOUNT INFORMATION

Location Name Lee's Summit Farmer's Market		
Contact Name	Contact Email	Phone
Service Address 209 SE Green St, Lee's Summit MO, 64063		

ASSEMBLY INFORMATION

Device Type RP	Make Watts	Model 957	Size 3	Serial Number YF-2816	Install Date 2025-06-02
Location Utility Room SE side of Building					

TESTING & MAINTENANCE

	Check Valve #1	Check Valve #2	Relief Valve	PVB/SVB	Shut Off Valves		
Initial Test	☒ Held at 8 PSID ☒ Closed Tight ☐ Leaked	☒ Held at 2.8 PSID ☒ Closed Tight ☐ Leaked	☒ Opened at 3 PSID ☐ Did Not Open	☐ Air Inlet Opened at PSID ☐ Opened Fully ☐ Check Held at PSID ☐ Leaked	Closed Tight Leaked	#1	#2
						☐	☐
REPAIR	☐ Cleaned Replaced: ☐ Disc ☐ Spring ☐ Guide ☐ Seat ☐ O-Ring(s) ☐ Module ☐ Rubber Kit ☐ Other	☐ Cleaned Replaced: ☐ Disc ☐ Spring ☐ Guide ☐ Seat ☐ O-Ring(s) ☐ Module ☐ Rubber Kit ☐ Other	☐ Cleaned Replaced: ☐ Disc ☐ Spring ☐ Diaphragm ☐ Seat ☐ O-Ring(s) ☐ Module ☐ Rubber Kit ☐ Other	☐ Cleaned Replaced: ☐ Air Inlet Disc ☐ Air Inlet Spring ☐ Check Disc ☐ Check Spring ☐ Float ☐ Diaphragm ☐ Rubber Kit ☐ Other			
	Final Test	PSID ☐ Closed Tight	PSID ☐ Closed Tight	Opened at PSID	Air Inlet PSID CK Valve PSID	Closed Tight	☐
Line Pressure at Time of Test		Test Date 2025-06-04		System Test Result Pass			
Remarks							

TESTER ATTESTATION, TEST KIT INFORMATION & TEST RESULTS

☒ The above report is certified to be true.			
Gauge Make N/A	Model N/A	Gauge No. 1377	Calibration Date 2024-07-30
Tester Name MATTHEW HUTFLES	Testing Company Name DMC SERVICE		Cert. No. 43-13634